

WHAT THE FIX?!

Model:

MINI (F54, F55, F56, F57, F60)
Mini Cabriolet, Clubman, Cooper,
Countryman, One
Motor B38

Trouble code:

- 118001
- Mixture adaptation: mixture too lean
- 118401
- Mix adaption: signal on the lean stop

MINI (F55)

Cooper; kW: 100

CARBURATION

Fault symptoms:

- Engine electronics indicator light is sporadically on.

Technical background:

Lambda control was checked.
The intake system was checked for leaks.
The exhaust system was checked for leaks.

Potential fix:

Replace tank ventilation solenoid valve.

