

WHAT THE FIX?!

Model:

6 (GJ, GL)
2.0 Petrol engine

Trouble code:

- P061B00
- Engine control unit: Internal fault in engine torque monitoring.

MAZDA

6 Kombi (GJ, GL); 2.0; kW: 107

ENGINE MANAGEMENT

Fault symptoms:

- Engine electronics indicator light has come on.
- Engine jerks after gear shift.

Technical background:

The error code indicates a defective engine control unit or damage to the electrical plug connections of the engine control unit. Engine wiring harness checked for damage. Sensors and actuators have been checked. Mass air flow meter defective.

Potential fix:

Replace air mass meter.

