

# WHAT THE FIX?!

## Model:

i30 (FD)

## Trouble code:

- P1690
- Immobiliser does not send feedback.

## HYUNDAI

*i30 (FD); 1.4 LPG; kW: 80*

## START SYSTEM

### Fault symptoms:

Engine does not start sporadically.

### Technical background:

Immobiliser reading coil has been replaced. Indicator light for immobiliser glows or lights up only briefly, even if the reading coil for immobiliser is not connected. Immobiliser wiring harness checked for damage. Electrical plug connection for immobiliser in the A-pillar below the glove compartment is corroded.

### Potential fix:

Clean the electric plug connection(s), repair if necessary.

